



Smith-Blair provided a 54” full circle wrap around clamp about 10 years ago. It was to be considered a temporary repair as the municipality had intentions to install a permanent repair within a year. This bell pack will encapsulate the stainless clamp. Note the bottom half of sleeve at beginning stages of installation process.

There was no need to shutoff this main water system which would have left a large portion of the population without water for a long period of time. Just imagine if the municipality had decided to replace this damaged section as they originally planned to do.

Smith-Blair knows no boundaries and continues to provide quality solutions to an ever demanding need to preserve the precious source of “Water”.

